UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,877,394 B2 **DATED** : April 12, 2005

INVENTOR(S) : Massey et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11,

Line 51, "pedal support having" should be -- pedal support portion having --.

Line 53, "being coupled" should be -- being pivotally coupled --.

Line 53, "lower" should be -- lower segment --.

Line 54, "about pivot" should be -- about a pivot --.

Column 16,

Line 12, "pedal" should be -- a pedal --.

Signed and Sealed this

Page 1 of 1

Fourteenth Day of February, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office